


PHOTOGRAPHS



Photograph 1. S-11519, Nassau Orchards Market, Roadside Produce Stand, front (south) and east sides, facing northwest.



Photograph 2. S-11519, Nassau Orchards Market, Roadside Produce Stand, rear (north) and east sides, facing west.



Photograph 3. S-11519, Nassau Orchards Market, pesticide storage shed and water tower, facing northeast.




Photograph 4. S-11519, Nassau Orchards Market, garage, facing southeast.



Photograph 5. S-11519, Nassau Orchards Market, house facade and garage addition, facing northwest.




Photograph 6. S-11519, Nassau Orchards Market, equipment barn, facing northwest.



Photograph 7. S-11519, Nassau Orchards Market, stable, facing west.



Photograph 8. S-8393, Belttown Historic District, the Nassau Colored School, facing northwest. The building is a contributing resource and also individually eligible for NRHP listing.



Photograph 9. S-8393, Belltown Historic District, house on lot 3-34-5-113, facing north. It corresponds to Plate 10 in the Tidlow et al. 1990 report. It is now evaluated as noncontributing due to alterations. Note the enclosed porch, replacement windows, and new siding.



Photograph 10. S-8393, Belltown Historic District, house on lot 3-34-5-115, facing northwest. It was evaluated as noncontributing in the original evaluation.



Photograph 11. S-8393, Belltown Historic District, house not included in the original Belltown Historic District boundary, facing northeast. It would be a contributing resource.



Photograph 12. S-8393, Belltown Historic District, house not included in the original Belltown Historic District boundary, facing northwest. It would be a contributing resource.




Photograph 13. S-8393, Belltown Historic District, house not included in the original Belltown Historic District boundary, facing west. It would be a contributing resource.



Photograph 14. S-8393, Belltown Historic District, house on lot 3-34-5-122, facing northwest. It replaced the contributing house shown as Plate 11 in the Tidlow et al. 1990 report.



Photograph 15. S-8393, Belltown Historic District, house on lot 3-34-5-124, facing northeast. Evaluated as a contributing resource in 1989, it has not substantially changed. The house is shown as Plate 12 in the Tidlow et al. 1990 report.



Photograph 16. S-8393, Belltown Historic District, house not included in the original Belltown Historic District boundary, facing northeast. It would be a contributing resource.




Photograph 17. S-8393, Belltown Historic District, building on lot 3-34-5-131, facing northeast. It is shown as Plate 10 in the Tidlow et al. 1990 report. Note the building's commercial use, and the large garage/industrial building that has been constructed to its rear.



Photograph 18. S-8393, Belltown Historic District, house on lot 3-34-5-133, facing northwest. It is shown as Plate 14 in the Tidlow et al. 1990 report. Originally evaluated as a contributing resource, it has not changed.



Photograph 19. S-8393, Belltown Historic District, house on lot 3-34-5-135.1, facing north. It is shown as Plate 11 in the Tidlow et al. 1990 report. Originally evaluated as a contributing resource, it has not changed.




Photograph 20. S-8393, Belltown Historic District, house on lot 3-34-5-134, facing northeast. Originally evaluated as a contributing resource. It corresponds to Plate 15 in the Tidlow et al. 1990 report. Note the large addition at the rear.



Photograph 21. S-8393, Belltown Historic District, house on lot 3-34-5-135, facing northeast. It replaced the contributing house shown as Plate 16 in the Tidlow et al. 1990 report.



Photograph 22. S-8393, Belltown Historic District, house on lot 3-34-5-139, facing northeast. It corresponds to Plate 18 in the Tidlow et al. 1990 report. Now evaluated as noncontributing due to substantial alterations, including the two-story addition, porch, and garage.



Photograph 23. S-8393, Belltown Historic District, house on lot 3-34-5-193, facing southeast. Evaluated as a contributing resource in 1989, it has not substantially changed. The house is shown as Plate 21 in the Tidlow et al. 1990 report.



Photograph 24. S-8393, Belltown Historic District, house on lot 3-34-5-2-2, facing southeast. Evaluated as a contributing resource in 1989, the house is shown as Plate 26 in the Tidlow et al. 1990 report. Note the large addition appended to the rear.



Photograph 25. S-8393, Belltown Historic District, noncontributing house and trailers that have replaced contributing resources on the south side of U.S. Route 9, facing southeast.



Photograph 26. S-8393, Belltown Historic District, view of the trailers that replaced contributing resources on the south side of U.S. Route 9, facing southwest.



Photograph 27. S-8393, Belltown Historic District, house on lot 3-34-5-214, facing east. Evaluated as contributing in 1989, the house has not changed. It is shown as Plate 33 in the Tidlow et al. 1990 report.




Photograph 28. S-8398, Belltown Historic District, John Wesley Methodist Episcopal Church, facing southeast. The building is a contributing resource and also individually eligible for NRHP listing.




Photograph 29. S-8393, Belltown Historic District, house on the Beaver Dam Road portion of lot 3-34-5-216, facing north. Evaluated as contributing in 1989, the house has not changed. It is shown as Plate 36 in the Tidlow et al. 1990 report.



Photograph 30. S-8393, Belltown Historic District, second house on the Beaver Dam Road portion of lot 3-34-5-216, facing north. Evaluated as contributing in 1989, the house has not changed. It is shown as Plate 35 in the Tidlow et al. 1990 report.



Photograph 31. S-8393, Belltown Historic District, house on lot 3-34-5-212, facing north. It corresponds to Plate 32 in the Tidlow et al. 1990 report. It is now evaluated as noncontributing due to alterations, including siding, replacement fenestration, and a new roof.



Photograph 32. S-8393, Belltown Historic District, house on lot 3-34-5-211, facing northwest. It replaced the contributing house shown as Plate 31 in the Tidlow et al. 1990 report.




Photograph 33. S-8393, Belltown Historic District, house on lot 3-34-5-210, facing west. Evaluated as contributing in 1989, the house has not changed. It is shown as Plate 30 in the Tidlow et al. report.




Photograph 34. S-8393, Belltown Historic District, showing a contributing house on lot 3-34-5-207 (middle house) and a noncontributing one on lot 3-34-5-206 (formerly a vacant lot), facing northeast.



Photograph 35. S-8393, Belltown Historic District, noncontributing house on lot 3-34-5-200, facing northwest.



Photograph 36. S-8393, Belltown Historic District, house on lot 3-34-5-198, facing west. It was originally evaluated as contributing, despite the one-story addition on the east side. It is shown as Plate 25 in the Tidlow et al. 1990 report.



Photograph 37. S-8393, Belltown Historic District, contributing house on lot 3-34-5-196, facing north. It is shown as Plate 23 in the Tidlow et al. 1990 report. Despite new siding and a roof, the house has not changed substantially.



Photograph 38. S-8393, Belltown Historic District, noncontributing trailer on lots 3-34-5-190 and 3-34-5-191, facing west.



Photograph 39. S-8393, Belltown Historic District, house on lot 3-34-5-190, facing north. It is shown as Plate 20 in the Tidlow et al. report, and was originally evaluated as a contributing resource despite the one-story garage addition and a second addition on the east side.



Photograph 40. S-8393, Belltown Historic District, house on lot 3-34-5-189, facing northwest. It is shown as Plate 19 in the Tidlow et al. 1990 report. The house has deteriorated markedly since that report was prepared, and the cross-gable jerkinhead roof has been replaced.




Photograph 41. S-900, Oakney Farmhouse, front and east side of the house, facing south. The portion extending from the rear is the original part of the house; the front portion dates to ca. 1919.



Photograph 42. S-900, Oakney Farmhouse, east side and rear of the house, facing west. The two-story horizontal portion is the original portion of the house.



Photograph 43. S-900, Oakney Farmhouse, west side and rear of the house, facing northeast. The two-story rear ell dates from ca. 1919, the one-story portion to 1954.




Photograph 44. S-900, Oakney Farmhouse, two nonhistoric garages located on the property, facing northeast.



Photograph 45. S-898, Norwood-Jackson Farm, north and front (west) sides of the farmhouse, facing southeast.



Photograph 46. S-898, Norwood-Jackson Farm, front (south) and east sides of the carriage barn, facing northwest.



Photograph 47. S-898, Norwood-Jackson Farm, south and rear (east) side of the barn, facing northwest.



Photograph 48. S-898, Norwood-Jackson Farm, concrete block milkhouse (left), wood frame workshop (center), and the corner of the modern barn, facing northwest.




Photograph 49. S-11730, Jimtown, house on Beaver Dam Road south of Jimtown Road, dating stylistically to the mid-1960s, facing southeast.




Photograph 50. S-11730, Jimtown, house on Beaver Dam Road south of Jimtown Road, facing southeast. It may have been built prior to 1963, but it has been altered.




Photograph 51. S-11730, Jimtown, house on Beaver Dam Road south of Jimtown Road, facing southeast. It was built after the 1963 cut-off date for the historic architectural resource survey.



Photograph 52. S-11730, Jimtown, Resource S-895, late nineteenth century farmhouse on Beaver Dam Road south of Jimtown Road, one of the early farmhouses of Jimtown, facing east.



Photograph 53. S-11730, Jimtown, late twentieth century house on Beaver Dam Road north of Jimtown Road, facing east.



Photograph 54. S-11730, Jimtown, late twentieth century house on Beaver Dam Road north of Jimtown Road, facing east.



Photograph 55. S-11730, Jimtown, late twentieth century house on the north side of Jimtown Road, facing northeast.



Photograph 56. S-11730, Jimtown, late twentieth century house on the north side of Jimtown Road, facing northeast.




Photograph 57. S-11730, Jimtown, altered mid-twentieth century house on the north side of Jimtown Road, facing northeast. The house has been nearly doubled in size.




Photograph 58. S-11730, Jimtown, late twentieth century house on the north side of Jimtown Road, facing northeast.



Photograph 59. S-11730, Jimtown, Resource S-11539, house on the south side of Jimtown Road, facing south. The house dates to the early 1950s.



Photograph 60. S-11730, Jimtown, late twentieth century trailer located on the north side of Jimtown Road, facing north.



Photograph 61. S-11730, Jimtown, late twentieth century trailer located on the north side of Jimtown Road, facing northeast.




Photograph 62. S-11730, Jimtown, Resource S-940, late nineteenth/early twentieth century house located on the south side of Jimtown Road, facing southwest.



Photograph 63. S-11730, Jimtown, Resource S-11540, facing southwest. The house, located on the south side of Jimtown Road, dates to the mid-twentieth century, but it was not moved to Jimtown until 1992.



Photograph 64. S-11730, Jimtown, house located on the north side of Jimtown Road, facing east. According to local informants, the house was in place in the early 1960s, but it has been expanded.



Photograph 65. S-11730, Jimtown, house located on the north side of Jimtown Road, facing north. According to local informants, the original part of the house dates to the mid-1960s, but it has been expanded.




Photograph 66. S-11730, Jimtown, house located on the north side of Jimtown Road, Facing north. According to local informants, the original part of the house dates to the Early 1960s; it appears to have been expanded.




Photograph 67. S-11730, Jimtown, house located on the south side of Jimtown Road, facing southwest. According to local informants, the house was expanded by building around a house dating from the early twentieth century.




Photograph 68. S-11730, Jimtown, Resource S-941, a house located on the south side of Jimtown Road, facing southwest. The one-story section on the left side of the photograph dates from the late twentieth century.




Photograph 69. S-11730, Jimtown, trailer located on the north side of Jimtown Road, facing east. The trailer was erected in the late twentieth century.




Photograph 70. S-11730, Jimtown, house located on the south side of Jimtown Road, facing southwest. The house was moved to Jimtown in the late twentieth century.




Photograph 71. S-11730, Jimtown, house located on the north side of Jimtown Road, facing northeast. According to local informants, the house was built in the 1950s but was then expanded.




Photograph 72. S-11730, Jimtown, house located on the south side of Jimtown Road, facing northeast. The house dates from the early 1960s; it replaced an older house.



Photograph 73. S-11730, Jimtown, house located on the north side of Jimtown Road, facing north. The modified double-wide trailer dates to the early 1960s.



Photograph 74. S-11730, Jimtown, late twentieth century trailer located on the north side of Jimtown Road, facing north.



Photograph 75. S-11730, Jimtown, house located on the south side of Jimtown Road, facing south. According to local informants, the house dates from the mid-twentieth century.



Photograph 76. S-11730, Jimtown, building located on the south side of Jimtown Road, facing southwest. Since this photograph was taken in July 2006, the building has either been replaced or so greatly expanded that it is unrecognizable.



Photograph 77. S-11730, Jimtown, Resource S-942, former house located on the north side of Jimtown Road, facing east. Built ca. 1920 and located near Goslee Creek, the house is abandoned and has nearly collapsed.



Photograph 78. S-947, Walls Farm, front (east) and north sides of the house as they appeared in December 2005, facing west. The larger portion of the original house extended to the north.




Photograph 79. S-947, Walls Farm, front (east) and north sides of the house with large addition under construction in September 2006, facing west.




Photograph 80. S-947, Walls Farm, south and rear (west) sides of the house as they appeared in December 2005, facing northeast.



Photograph 81. S-947, Walls Farm, rear (west) side of the house as it appeared in September 2006, facing southeast.




Photograph 82. S-947, Walls Farm, barn showing siding and large one-story addition to the north side, facing north.



Photograph 83. S-947, Walls Farm, shed on the property, facing west.



Photograph 84. S-951, Joseph Farm, farmhouse front (west) and south sides, facing east.



Photograph 85. S-951, Joseph Farm, summer kitchen behind the farmhouse, facing southeast.




Photograph 86. S-951, Joseph Farm, remainder of the barn, facing north.



Photograph 87. S-951, Joseph Farm, north side of the farmhouse, summer kitchen, cold cellar, and outhouse, facing southeast.




Photograph 88. S-951, Joseph Farm, chicken coop (1929), facing west.




Photograph 89. S-951, Joseph Farm, vehicle shelter (ca. 2000), facing east.



Photograph 90. S-951, Joseph Farm, storage building (ca. 1980), Quonset hut (ca. 1980), storage building (ca. 1995), and garage (ca. 1995), facing northeast.



Photograph 91. S-951, Joseph Farm, mobile home (ca. 2000), facing northeast.



Photograph 92. S-951, Joseph Farm, storage shed (ca. 2000), facing northwest.



Photograph 93. S-951, Joseph Farm, house moved onto the property (ca. 2000), facing southwest.



Photograph 94. S-951, Joseph Farm, mobile home now used as the farmhouse for the property, facing southeast.



Photograph 95. S-7911, Holland Cemetery, graves facing Sarah Waples and John Holland (upright gravestones), with Betsey and Isaac Hollands' gravestones on the ground, facing northwest.



Photograph 96. S-9711, Holland Cemetery, graves of John Holland (foreground) and Jean Holland (background), facing northeast.



Photograph 97. S-11548, Ebenezer Methodist Episcopal Church Cemetery, from the southwest corner of the cemetery, facing northeast.



Photograph 98. S-11548, Ebenezer Methodist Episcopal Church Cemetery, from the northwest corner of the cemetery, facing south.



Photograph 99. S-966, Hart Farm, facade of the farmhouse, facing southwest.




Photograph 100. S-966, Hart Farm, facade and south side, facing northwest.




Photograph 101. S-966, Hart Farm, barn and carriage house, facing west.



Photograph 102. S-966, Hart Farm, front (east) and south sides of the barn, facing north.




Photograph 103. S-966, Hart Farm, shed on the property, facing northwest.




Photograph 104. S-8591, Israel United Methodist Church, front (south) and west sides, facing northeast. Note also the cemetery surrounding the church.



Photograph 105. S-8591, Israel United Methodist Church, rear (north) and east sides, facing southwest.



Photograph 106. S-8591, Israel United Methodist Church, interior from the corner of the altar toward the rear of the church, facing southeast.



Photograph 107. S-8591, Israel United Methodist Church, interior from the back of the church toward the altar and choir, facing north.



Photograph 108. S-8591, Israel United Methodist Church, detail of the window and surround, facing west.